




Wiring diagram RZ350YPVS - PCDI-10V

PV servo



B - BLACK
Br - BROWN
L - BLUE
G - GREEN
Gr - GREY
O - ORANGE
R - RED
V - VIOLET
W - WHITE
Y - YELLOW

